


CAS-3261 Pole Thin Direct Mounting

Product Guide:



- CAS-3261
- with stainless steel straps x4
- M8x16 screw x4
- washer x4
- spring washer-8 x4

•

Installation steps:

- 1. Fasten the Pole Thin Direct Mounting on a pole with equipped stainless straps.
- 2. Run the cable(s) through the hole on the Pole Thin Direct Mounting.
- 3. Fasten the CAS-3201 Mini Pendant (Optional Accessories) Mount onto the Pole Thin Direct Mounting with the supplied screws and washers. Then thread the cable(s) through the CAS-3201 Mini Pendant (Optional Accessories) Mount with the cable(s) coming out of the Pendent Mount's outlet.
- 4. Attach the Waterproof Rubber to the CAS-3201 Mini Pendant (Optional Accessories).
- 5. Thread the cable(s) through the Pole Thin Direct Mounting and join the Pole Thin Direct Mounting to the CAS-3201 Mini Pendant (Optional Accessories) with the supplied screws and washers. Then adjust the Waterproof Rubber to the joint.
- 6. Connect the cable(s) to the Dome Camera.
- 7. Join the Dome Camera to the Pole Thin Direct Mounting with the supplied screw and washers.