

Release Notes

FCS-5004/8 Version 1.3.2

New Functions

1. New SMS service provider supported: Italy Vola. Website: <http://www.vola.it>.
2. PTZ camera control
 - Merit Lilin speed dome has added preset function.
 - Pelco-D, Merit Lilin, and DynaColor speed dome have added speed adjustment function.

Fixed Problems

1. When recording in FTP mode, all files will be deleted and only the video recorded for the last hour will remain.
2. Recording files cannot be overwritten when the files are saved on LevelOne NAS of version 2.27.2, or 3.10.2 or later versions if user quota has not been set for the user account.
3. Playback of recording files via external network cannot be executed properly when FCS-5004/8 is configured as virtual server via a router.